

Work Order ID 78220***78220***

Page 1

Friday, February 03, 2012 12:42:02 PM

Item ID: D206-642-249

Accept

N900040100Setup Start ***NS1***

Revision ID:

Stop ***NS2***

Item Name: Run-on Landing Wearplate

Start Date: 1/2/2012 Start Qty: 1.00

1

Cust Item ID:

Required Date: 1/3/2012 Req'd Qty: 1.00

1

Customer: CU-DAR001

Reference: RMA RA111299 - **RETURN**Approvals: Process Plan: **MF**Date: **12-02-03** Tooling:

Date:

Run Start ***NR1***

QC:

Date: SPC (Y/N):

Date:

Stop ***NR2***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	---------	--------	--------------	---------------	---------------	------------------	----------------

Draw Nbr

Revision Nbr

IIN-D206-642

0

100

0.00

100

QC

Quality Control

Memo

0.00

INSPECT RA 111299 D206-642-249 B74532

KIT IS COMPLETE

NEEDS NEW PAPERWORK AND LABELS

110

Identify as per dwg & Stock Location: 0.00

110

Packaging

Packaging

Memo

0.00

ID AND STOCK UNDER NEW BATCH NUMBER

CHG001

Work Order ID 78220***78220***

Page 2

Friday, February 03, 2012 12:42:02 PM

Item ID: D206-642-249

Accept

N900040100Setup Start ***NS1***

Revision ID:

Stop ***NS2***

Item Name: Run-on Landing Wearplate

Start Date: 1/2/2012 Start Qty: 1.00

1

Cust Item ID:

Required Date: 1/3/2012 Req'd Qty: 1.00

1

Customer: CU-DAR001

Reference: RMA RA111299

Approvals: Process Plan:

Date:

Tooling:

Date:

Run Start ***NR1***

QC:

Date:

SPC (Y/N):

Date:

Stop ***NR2***Sequence ID/
Work Center IDOperation
DescriptionSet Up/
Run Hours

Tool ID

Tool #

Plan
CodeAccept
QtyReject
QtyReject
NumberInsp.
Stamp

120

QC21- Final Inspection - Work Order Release

0.00

120

QC

Memo

0.00

Quality Control

M.L.T. 12/02/06

MF

12-02-06

RA 111299 D206-642-249

B74532

Received @ Dart December 19th, 2011
Inspected@ Dart December 29th, 2011

Instructions for RA111299 D206-642-249 B74532 CHG001

- Kit is complete
- Needs new paper work and labels
- Needs new **BATCH #**
- Needs new work order to be put back in to stock

Time Estimate _____ = **1 HOUR ONLY** (stores only)

Departments Required: Stores

Pictures Attached _____ = N/A

**THIS INSTRUCTION SHEET MUST
BE ATTACHED TO THE
RESTOCKING WORK ORDER AT
ALL TIMES!!!!**